Digital Thermo-hygrometer manual CH-905

一、Specifications:

Temperature Range: $-10^{\circ}\text{C}-50^{\circ}\text{C}$ (14°F ~ 122°F)

Humidity Range: 10%-99%

Temperature Accuracy: ±1 °C at 0 °C ~40 °C, ±2 °C at other range Humidity Accuracy: ±5% 40%~80% at 25 °C, ±8% at other range

Resolution: Temperature 1°C, Humidity 1%RH

Unit Size: 93.5×114.5×22mm

N.W.:130a

Power supply: 1*1.5V(AAA) battery

二、Features:

- 1. Large LCD, display temperature, humidity, simple operation.
- 2. Temperature $^{\circ}$ C / $^{\circ}$ F switch function, can choose display Celsius or Fahrenheit to meet different people's habits.
- 3 MAX/MIN temperature & humidity memory function, clear memory function, restart function.
- 4 . Have bracket and hanging hole behind the product, can be placed standing or hanging.
- 5. Low power consumption, high precision and high stability

三、Operation Instruction:

Open the battery tank and take out the insulator(install the battery), current temperature and humidity will display when powered on.

- (一) Front buttons: "MAX/MIN""CLEAR""℃/F"
- 1. Press"MAX/MIN", the record of highest and lowest temperature and humidity from powered on can be check.
- 2. Press"CLEAR", clear the memory value.
- 3、Press" \mathbb{C}/\mathbb{F} ", choose display Celsius or Fahrenheit.
 - (二) Back button: "RESET"

Press"RESET", restore the factory default settings.

Notes:

- 1. When the digital display becomes faint, the battery needs to be replaced to keep accuracy.
- 2. The MAX/MIN memory will be cleared away when battery is re-installed